

CHIRP - Bug # 2681

Status:	New	Priority:	Normal
Author:	Wolfgang Baumgaertel	Category:	
Created:	06/28/2015	Assignee:	
Updated:	06/28/2015	Due date:	
Chirp Version:	0.4.0		
Model affected:	Boafeng UV-5RCHP		
Platform:	Linux		
Subject:	Boafeng UV-5RCHP not working		
Description			
<p>I have two UV-5Rs and one is working(older UV-5R) - one not(new UV-5RCHP)</p> <p>I bought the UV-5R at ebay some month ago and the UV-5RCHP at the Ham-Radio in Friedrichshafen yesterday.</p> <p>The UV-5R works like a charm. But the UV-5RCHP does not .</p> <p>Chirp 0.4.0 AND Chirp 0.4.1: Download works!!! Upload gives: Unsupported firmware version: `N5R3405BFP3-23\Uffffff\Uffffff`</p> <p>Chirp daily-20150623: No download: Incorrect 'Model' selected No upload: Upload is grayed out.</p> <p>Holding '3' while powering up: UV-5R: BFS279 UV-5RCHP: BFP3-23</p> <p>Holding '6' while powering up: UV-5R: 140320N UV-5RCHP: 150121N</p> <p>Serial Numbers: UV-5R: 130U707150 UV-5RCHP: IL1503HP0231</p> <p>-- 73 de Wolfgang, dl7nb</p>			

History
