

CHIRP - Bug # 2971

Status:	Closed	Priority:	Normal
Author:	Paulo Henrique	Category:	
Created:	11/03/2015	Assignee:	
Updated:	10/01/2020	Due date:	
Chirp Version:	daily		
Model affected:	Yaesu FT-2900		
Platform:	Windows		
Subject:	2900 error		
Description			
<p>I'm getting this error when checking the radio http://i.imgur.com/AHogTzf.png is there any way to help to tackle this? because shirp does not detect the radio.</p>			

History

#1 - 04/28/2020 05:54 pm - Bernhard Hailer

- Tracker changed from Feature to Bug
- Status changed from New to Feedback
- Target version changed from 0.5.0 to chirp-daily
- Model affected changed from (All models) to Yaesu FT-2900
- Platform set to Windows

Have you been able to resolve this on your own since you submitted this?

Have you tried with a recent version since you submitted this?

If you haven't, and if you're still having this issue, please refer to the Wiki "[[How To Report Issues]]" and provide a debug log. Thanks!

#2 - 08/23/2020 10:36 pm - Bernhard Hailer

Paulo, is this actually anything which has to do with Chirp? It doesn't look like it?

#3 - 10/01/2020 03:54 pm - Bernhard Hailer

- Status changed from Feedback to Closed

No more feedback by submitter.