

CHIRP - Bug # 2983

Status:	Rejected	Priority:	Low
Author:	josh assing	Category:	
Created:	11/07/2015	Assignee:	
Updated:	11/08/2015	Due date:	
Chirp Version:	0.4.0		
Model affected:	TYT TH 9800		
Platform:	Windows		
Subject:	TH 9800 can't communicate		
Description			
<p>I have a brand new TH9800. ("Plus" version, direct from TYT last week.) I am using a legal ftdi chip cable on COM7 When I try to download from the radio, it instantly tells me that it cannot communicate.</p>			
Related issues:			
related to Bug # 4563: TYT TH-9800+ (PLUS version) - Failed to communicate wi...		Feedback	02/26/2017

History

#1 - 11/07/2015 09:27 pm - josh assing

|| Can close as hardware specific <<

I tried on a different win8.1 machine with same cable & software versions and it connected no problem. Problem machine is an older hp laptop...
Sorry for the false report -- should have tested a different machine right away.

#2 - 11/08/2015 12:17 am - Filippi Marco

- Status changed from New to Rejected

User says it's hardware issue