

CHIRP - Bug # 3075

Status:	Closed	Priority:	Normal
Author:	Charles Morse	Category:	
Created:	12/18/2015	Assignee:	
Updated:	04/23/2020	Due date:	
Chirp Version:	daily		
Model affected:	Luiton LT-898UV		
Platform:	Windows		
Subject:	Luiton LT-898UV settings		
Description			
<p>just got one the chirp dose not have the option for the extras that the software from the company dose but there software wont read or wright to the radio can you fix that it would be great thank you</p>			

History

#1 - 01/29/2020 05:31 pm - Bernhard Hailer

- Tracker changed from Bug to Feature
- Subject changed from Luiton LT-898uv to Luiton LT-898UV settings
- Status changed from New to Feedback
- Priority changed from High to Normal
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Model affected changed from Luiton lt-898uv to Luiton LT-898UV

Have you tried with a recent version of Chirp, is this still an issue?

#2 - 04/23/2020 03:45 pm - Bernhard Hailer

- Tracker changed from Feature to Bug
- Status changed from Feedback to Closed
- Platform set to Windows

No more feedback by submitter.