

## CHIRP - Bug # 3391

<b>Status:</b>	New	<b>Priority:</b>	High
<b>Author:</b>	Patrick Joles	<b>Category:</b>	
<b>Created:</b>	02/24/2016	<b>Assignee:</b>	
<b>Updated:</b>	12/29/2016	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Model affected:</b>	ID-51A Plus		
<b>Platform:</b>	Linux		
<b>Subject:</b>	Missing Tone Value 254.1 - ID-51A Plus		
<b>Description</b>			
The Tone Value only goes up to 250.3 and not 254.1, on the ICOM ID-51A Plus, please correct. Thanks			

### History

#### #1 - 03/12/2016 02:35 am - K. Arvanitis

Hi Patrick, can you attach an image of your radio to the bug?

#### #2 - 03/16/2016 09:16 pm - Patrick Joles

- File *Chirp-Base-Dwnld-23.FEB.2016.csv* added

#### #3 - 03/16/2016 09:17 pm - Patrick Joles

K. Arvanitis wrote:

| *Hi Patrick, can you attach an image of your radio to the bug?*

Done - Patrick

#### #4 - 07/13/2016 06:11 am - Patrick Joles

Any Update on this bug?

#### #5 - 12/29/2016 08:52 am - Patrick Joles

Patrick Joles wrote:

| *K. Arvanitis wrote:*

| | *Hi Patrick, can you attach an image of your radio to the bug?*

| *Done - Patrick*

Any Update?

**Files**

Chirp-Base-Dwnld-23.FEB.2016.csv

2.4 kB

03/16/2016

Patrick Joles