

CHIRP - Bug # 3579

Status:	New	Priority:	Normal
Author:	bob bob	Category:	
Created:	04/15/2016	Assignee:	
Updated:	04/15/2016	Due date:	
Chirp Version:	0.4.0		
Model affected:	(All models)		
Platform:	Windows		
Subject:	UV-5R_frequency_limits		
Description			
<p>Hello!</p> <p>I found one bug. I need to scan the band 144 to 146MHz in UV-5R radio.</p> <p>Upper frequency need to wright in to register 144-145 and than he scanning in necessary band 144-146MHz.</p> <p>Kind regards</p>			

History
