

CHIRP - Bug # 3579

Status:	Closed	Priority:	Normal
Author:	bob bob	Category:	
Created:	04/15/2016	Assignee:	
Updated:	01/27/2020	Due date:	
Chirp Version:	daily		
Model affected:	Baofeng UV-5R		
Platform:	Windows		
Subject:	UV-5R_frequency_limits		
Description			
<p>Hello!</p> <p>I found one bug. I need to scan the band 144 to 146MHz in UV-5R radio. Upper frequency need to wright in to register 144-145 and than he scanning in necessary band 144-146MHz.</p> <p>Kind regards</p>			
Related issues:			
duplicates Bug # 3581: Baofeng UV-5R frequency limits		Closed	04/15/2016

History

#1 - 01/27/2020 05:04 pm - Bernhard Hailer

- Status changed from New to Closed
- Target version changed from 0.4.1 to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Model affected changed from (All models) to Baofeng UV-5R

Duplicates #3581.