

CHIRP - New Model # 3583

| | | | |
|--------------------------------|--|------------------|--------|
| Status: | Feedback | Priority: | Normal |
| Author: | Austin K | Category: | |
| Created: | 04/15/2016 | Assignee: | |
| Updated: | 02/13/2020 | Due date: | |
| Chirp Version: | daily | | |
| Equipment Loan Offered: | No | | |
| Subject: | HYS TC-P10W | | |
| Description | <p>I have a new brand for you guys to add to your lists. It's one of the Chinese's HYS series (HYS TC-P10W). Not sure how to upload the RAR since it is too big. Just let me know if you need it. Thanks in advance.</p> | | |

History

#1 - 02/13/2020 01:45 pm - Bernhard Hailer

- Status changed from New to Feedback
- Assignee deleted (Austin K)
- Priority changed from Urgent to Normal
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily

The addition of a new radio to Chirp requires two things:

- 1) a volunteer developer who takes the task to work on this driver,
- 2) availability of test equipment, such as a loaner radio (see [\[\[Rules For Loaning A Radio\]\]](#)).

Unfortunately, you need to wait until both conditions have been met.