

CHIRP - Bug # 3717

Status:	Feedback	Priority:	Normal
Author:	Danny White	Category:	
Created:	06/06/2016	Assignee:	
Updated:	08/29/2020	Due date:	
Chirp Version:	daily		
Model affected:	Icom ID-880H		
Platform:	MacOS		
Subject:	Freezes upload on Icom ID-880H		
Description			
<p>I was able to download from my transceiver onto the CHIRP software but when I try to upload changes onto the equipment it freezes at about 1/5 the way in. Rebooting the radio results in all memories being erased. Assuming that it was a change I'd made that was causing the issue, I downloaded the radio again and without making any changes, immediately attempted the upload. Same result. Please help.</p>			

History

#1 - 04/25/2020 09:14 pm - Bernhard Hailer

- Status changed from New to Feedback
- Chirp Version changed from 0.4.0 to daily

Have you been able to resolve this on your own since you submitted this?

Have you tried with a recent version since you submitted this?

If you haven't, and if you're still having this issue, please refer to the Wiki "[[How To Report Issues]]" and provide a debug log. Thanks!

#2 - 08/29/2020 03:38 pm - Bernhard Hailer

- Target version set to chirp-daily

Please try with a recent version of Chirp, the Icom driver has been reviewed.