

## CHIRP - Bug # 4055

<b>Status:</b>	Closed	<b>Priority:</b>	Normal
<b>Author:</b>	tyler m	<b>Category:</b>	
<b>Created:</b>	09/23/2016	<b>Assignee:</b>	
<b>Updated:</b>	02/07/2020	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Model affected:</b>	Baofeng UV-5RV2+		
<b>Platform:</b>	Windows		
<b>Subject:</b>	Error Message "Failed to communicate with radio: local variable 'response' referenced before assignment"		
<b>Description</b>	I just purchased a BaoFeng UV-5RV2+ and am attempting to use CHRIP to program it and i cant because i keep getting this error.		
<b>Related issues:</b>	related to Bug # 3987: UV-82HP (An error has occurred, Unexpected response f... <b>Closed</b> <b>09/04/2016</b>		

### History

#### #1 - 09/23/2016 05:13 pm - tyler m

- File *debug.log* added

Attached the Debug file

#### #2 - 09/24/2016 06:48 am - Jim Unroe

- Status changed from *New* to *Feedback*

Tyler,

I submitted a patch for this yesterday afternoon and today's CHIRP daily build should have resolved the issue. Please try it and let me know if it works for you.

Jim KC9HI

#### #3 - 09/24/2016 08:11 am - tyler m

Thank you so much, I am now able to use CHIRP. Thanks for the quick update!

#### #4 - 09/24/2016 09:06 am - Tim McLean

I just wanted to say thanks to Tyler for reporting and thanks to Jim for updating. I had this exact same issue last night and was about to tear into my cable to troubleshoot and this solved my issue...so THANKS!!!

#### #5 - 02/07/2020 01:58 pm - Bernhard Hailer

- Status changed from *Feedback* to *Closed*

- Priority changed from *Urgent* to *Normal*

- Target version set to *chirp-daily*

- Chirp Version changed from *0.4.0* to *daily*

- Model affected changed from (All models) to Baofeng UV-5RV2+

Resolved.

**Files**

---

debug.log	32.5 kB	09/23/2016	tyler m
-----------	---------	------------	---------