

## CHIRP - Bug # 4389

<b>Status:</b>	Resolved	<b>Priority:</b>	Low
<b>Author:</b>	Aaron P	<b>Category:</b>	
<b>Created:</b>	01/09/2017	<b>Assignee:</b>	Aaron P
<b>Updated:</b>	07/21/2018	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Model affected:</b>	TH-D74		
<b>Platform:</b>	Linux		
<b>Subject:</b>	Kenwood TH-D74 USB device not discoverable		
<b>Description</b>			
<p>At least on Ubuntu 14.04 the TH-D74 enumerates as /dev/ACM*</p> <p>kernel: [22991.102604] usb 3-2: new full-speed USB device number 2 using xhci_hcd kernel: [22991.236491] usb 3-2: not running at top speed; connect to a high speed hub kernel: [22991.253618] usb 3-2: New USB device found, idVendor=2166, idProduct=600b kernel: [22991.253621] usb 3-2: New USB device strings: Mfr=1, Product=2, SerialNumber=0 kernel: [22991.253623] usb 3-2: Product: TH-D74 kernel: [22991.253624] usb 3-2: Manufacturer: JVC KENWOOD kernel: [22991.255719] cdc_acm 3-2:1.0: ttyACM1: USB ACM device</p>			

### Associated revisions

Revision 2833:3009f7e686df - 01/09/2017 08:17 pm - Aaron P

[TH-D74] Allow selection of /dev/ACM\* Fixes #4389

### History

#1 - 03/10/2017 01:00 pm - Aaron P

- Status changed from New to Resolved

Closed. Resolved.

#2 - 07/21/2018 06:29 pm - Emilio Recio

What's the status of this request? I just got the TH-D74A radio, and D72 is supported but not the D74.