

CHIRP - Bug # 4527

Status:	Closed	Priority:	Normal
Author:	Jess Haas	Category:	
Created:	02/13/2017	Assignee:	Rick DeWitt
Updated:	01/16/2021	Due date:	01/16/2021
Chirp Version:	daily		
Model affected:	(All models)		
Platform:	Windows		
Subject:	Can't program 1200mhz frequencies into memory on D710		
Description	I can program them fine on the radio and chirp reads them fine but chirp fails to write one to memory whenever I try.		

History

#1 - 01/15/2021 09:55 am - Rick DeWitt

- Assignee set to Rick DeWitt
- Chirp Version changed from 0.4.0 to daily

I will look into this. Possibly fixed in clone-mode driver release.

#2 - 01/16/2021 10:06 am - Rick DeWitt

- Due date set to 01/16/2021
- Status changed from New to Closed
- Target version set to chirp-daily
- % Done changed from 0 to 100
- Estimated time set to 0.16

This feature (1200 MHz band) works fine in CloneMode.