

CHIRP - New Model # 4723

Status:	Closed	Priority:	Normal
Author:	Eddie DeYoung	Category:	
Created:	04/12/2017	Assignee:	
Updated:	02/11/2020	Due date:	
Chirp Version:	daily		
Equipment Loan Offered:	No		
Subject:	Baofeng GT-5TP		
Description	none of the models listed will work with this model (at least not mine)... I think it is a driver issue? Using WIN10PE		
Related issues:	duplicates Bug # 4569: Baofeng GT-5TP Closed 02/28/2017		

History

#1 - 02/07/2020 01:54 pm - Bernhard Hailer

- Subject changed from Bafeng GT-5TP to Baofeng GT-5TP
- Status changed from New to Feedback
- Assignee deleted (Eddie DeYoung)
- Priority changed from Urgent to Normal
- Target version changed from 0.5.0 to chirp-daily

Depending on the number of power levels, try a recent version of Chirp and the Baofeng UV-5R driver (2 power levels), or the UV-82HP (3 levels). The GT-5TP is often mentioned in Chirp tickets, you might want to search for it for further pointers.

#2 - 02/11/2020 01:18 pm - Bernhard Hailer

- Status changed from Feedback to Closed

Also see #4569.

Try using the Baofeng UV-82HP selection in Chirp.