

CHIRP - Feature # 4773

Status:	New	Priority:	Normal
Author:	Takayoshi SASANO	Category:	
Created:	04/28/2017	Assignee:	
Updated:	04/17/2020	Due date:	
Chirp Version:	daily		
Model affected:	ICOM IC-208		
Subject:	IC-208: cannot disable high-speed cloning		
Description	<p>IC-208 has high speed cloning feature and CHIRP always use it. If IC-208 supports normal speed (9600bps) cloning, we have to add rf.has_settings = True in def get_features(self) to select the speed.</p> <p>Users can select cloning speed with all other ICOM's rigs which supports high speed cloning.</p>		
Related issues:	related to Feature # 4771: IC-P7: high speed (38400bps) cloning New 04/28/2017		

History

#1 - 04/17/2020 08:21 pm - Bernhard Hailer

- Tracker changed from Bug to Feature
- Target version set to chirp-daily