

CHIRP - New Model # 4835

Status:	New	Priority:	Normal
Author:	Tony Bucci	Category:	
Created:	05/22/2017	Assignee:	
Updated:	03/13/2020	Due date:	
Chirp Version:	daily		
Equipment Loan Offered:	No		
Subject:	Baofeng BF-888S Plus		
Description	<p>I have seen that the BF-888S Plus is not supported by chirp... I was able to get the requested portmon from an 32bit XP machine. They are attached.</p> <p>Please let me know if I can provide any more details.</p> <p>Thanks,</p> <p>Tony</p>		
Related issues:			
duplicated by Bug # 4565: BF-888S and BF-888S Plus Fail To Intialize 50% Of Time		Feedback	02/26/2017
duplicated by New Model # 3651: 2016 BF-888s Plus		Closed	05/15/2016

History

#1 - 03/13/2020 06:14 pm - Bernhard Hailer

- Subject changed from BF-888S Plus Read / Write from OEM software to Baofeng BF-888S Plus
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily

Files

bf-888s_plus_read.LOG	592.3 kB	05/22/2017	Tony Bucci
bf-888s_plus_write.LOG	2 MB	05/22/2017	Tony Bucci