

## CHIRP - Bug # 5057

<b>Status:</b>	Closed	<b>Priority:</b>	Normal
<b>Author:</b>	Vincent Orfano	<b>Category:</b>	
<b>Created:</b>	08/11/2017	<b>Assignee:</b>	
<b>Updated:</b>	05/01/2020	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Model affected:</b>	Baofeng UV-5R		
<b>Platform:</b>	MacOS		
<b>Subject:</b>	BF UV5R issues with Mac OS Sierra 10.12		
<b>Description</b>			
<p>Hi everyone,</p> <p>New to the world of amateur radio and was received a brand new Baofeng UV-5R just like this one: <a href="https://www.amazon.com/gp/product/B06X6GS3RF/ref=oh_aui_detailpage_o00_s00?ie=UTF8&amp;#38;psc=1">https://www.amazon.com/gp/product/B06X6GS3RF/ref=oh_aui_detailpage_o00_s00?ie=UTF8&amp;#38;psc=1</a></p> <p>I've followed the directions provided by the link below however I am unable to clone the radio and the "An error has occurred" notice comes up. <a href="http://chirp.danplanet.com/projects/chirp/wiki/MacOS_Tips">http://chirp.danplanet.com/projects/chirp/wiki/MacOS_Tips</a></p>			

### History

#### #1 - 03/02/2020 04:18 pm - Bernhard Hailer

- Status changed from New to Feedback
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Model affected changed from (All models) to Baofeng BF UV-5R
- Platform changed from Windows to MacOS

Could you please provide a debug log as described in the Wiki: [[How To Report Issues]]? Thanks!

#### #2 - 05/01/2020 10:16 pm - Bernhard Hailer

- Status changed from Feedback to Closed
- Model affected changed from Baofeng BF UV-5R to Baofeng UV-5R

No more feedback by submitter.