

## CHIRP - Bug # 5073

<b>Status:</b>	Closed	<b>Priority:</b>	Normal
<b>Author:</b>	Christopher Cancilla	<b>Category:</b>	
<b>Created:</b>	08/15/2017	<b>Assignee:</b>	
<b>Updated:</b>	03/02/2020	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Model affected:</b>	Baofeng UV-3R		
<b>Platform:</b>	Windows		
<b>Subject:</b>	UV-3R Offset and Step incorrect		
<b>Description</b>			
<p>When uploading to the radio, the step for the offset is not english, I mean there are letters, sorta, but you cannot read them until you spin the knob.</p> <p>As for the Offset, if you set it to .6MHz, on the screen in CHIRP; it transfers to the radio as 60.00MHz.</p> <p>If you need more information, let me know.</p> <p>I am running:</p> <p>CHIRP daily-20170714, GTK 2.24.10 PyGTK 2.24.0 Python 2.7.10</p> <p>Thanks,</p> <p>Chris Cancilla, W4CEC 678-371-5031 cell <a href="mailto:W4CEC@arrl.net">W4CEC@arrl.net</a></p>			
<b>Related issues:</b>			
duplicates Bug # 4635: Baofeng UV-3R Plus Repeater Offset Error		<b>Feedback</b>	<b>03/16/2017</b>

### History

#### #1 - 05/11/2018 02:42 pm - Richard Menedetter

This ticket is a duplicate of Bug #4635

#### #2 - 03/02/2020 04:24 pm - Bernhard Hailer

- Status changed from New to Closed
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Model affected changed from (All models) to Baofeng UV-3R

Duplicates #4635. Please leave further feedback there. Thanks!