

CHIRP - Bug # 5269

Status:	Closed	Priority:	Normal
Author:	Jeremy Cook	Category:	
Created:	10/22/2017	Assignee:	
Updated:	03/03/2020	Due date:	
Chirp Version:	daily		
Model affected:	Rugged Radio RM-25R		
Platform:	Windows		
Subject:	Programming Rugged Radio RM-25R. Radio is similar to QYT8900, Wacom mini 8900.		
Description			
<p>I'm trying to program my mobile rugged radio RM-25R. There is no software on chirp for this model. However, this is the same radio as the QYT8900, Wacom Mini 8900 and Juentai JT-6188 mini. When I tried to read the radio the using the QYT9900 on chirp, it said to try Wacom 8900. Once I did that you can see the status bar loading the radio info. But then I get an error saying radio the did not enter clone mode. Do I need to have software for rugged or can I use the Wacom? Do I need to select anything in the radio menu at all?</p>			

History

#1 - 10/23/2017 02:28 am - Jim Unroe

- Status changed from New to Feedback

Please include a debug.log file. How to locate the debug.log file is explained on the [How to report issues](#) wiki page.

Jim

#2 - 03/03/2020 05:18 pm - Bernhard Hailer

- Status changed from Feedback to Closed

- Target version set to chirp-daily

- Chirp Version changed from 0.4.0 to daily

- Model affected changed from (All models) to Rugged Radio RM-25R

No more feedback by submitter.