

CHIRP - Bug # 5341

Status:	Closed	Priority:	Normal
Author:	Doug Gerard	Category:	
Created:	11/13/2017	Assignee:	
Updated:	03/04/2020	Due date:	
Chirp Version:	daily		
Model affected:	Baofeng UV-6R		
Platform:	Windows		
Subject:	Baofeng UV-6R unable to detect model		
Description			
I think I need to add this as a new model request, considering the issues I have had (see bug reports 5217 and 5247) and the fact that I received a message on connection that this model is not recognized. Lack of a usable squelch is very annoying...			
Related issues:			
related to Bug # 5217: Welcome message not able to be changed and radio image...		Closed	10/01/2017

History

#1 - 11/15/2017 05:00 pm - Doug Gerard

- File *Baofeng_UV-6R_20171014.img* added

Attaching image as instructed by Chirp when encountering the error message "unable to detect model" while loading a saved image from this radio.

#2 - 02/07/2020 01:25 pm - Bernhard Hailer

- Tracker changed from *New Model* to *Bug*
- Subject changed from *UV6R* to *Baofeng UV-6R unable to detect model*
- Status changed from *New* to *Feedback*
- Priority changed from *Urgent* to *Normal*
- Target version set to *chirp-daily*
- Chirp Version changed from *0.4.0* to *daily*
- Model affected set to *Baofeng UV-6R*
- Platform set to *Windows*

Actually, this radio is supposed to be supported. I converted this to a bug report.

What we need is a debug log, please refer to the Wiki [\[\[How To Report Issues\]\]](#).

#3 - 03/04/2020 02:42 pm - Bernhard Hailer

- Status changed from *Feedback* to *Closed*

No more feedback by submitter.

Files

Baofeng_UV-6R_20171014.img	8 kB	11/15/2017	Doug Gerard
----------------------------	------	------------	-------------