

CHIRP - Bug # 5445

Status:	Closed	Priority:	Normal
Author:	Demetre Koumanakos	Category:	
Created:	12/19/2017	Assignee:	
Updated:	09/10/2020	Due date:	
Chirp Version:	daily		
Model affected:	Icom IC-E7, IC-P7		
Platform:	MacOS		
Subject:	IC-E7 (P7) fails upload data on Mac		
Description			
<p>Hi,</p> <p>I installed Chirp on a mid-2012 MBP i7 running 10.12.6 with a generic usb cable. Download memory with Icom IC-E7 (P7) and Baofeng UV-5RE with no problem.</p> <p>Upload worked with Baofeng, but not Icom. After Icom failed Chirp require forced quit, and MBP required restart for Chirp to be able to run again.</p>			
Related issues:			
related to New Model # 2253: Icom IC-E7		New	01/24/2015

History

#1 - 02/18/2020 03:12 pm - Bernhard Hailer

- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Model affected changed from (All models) to Icom IC-E7, IC-P7

#2 - 05/06/2020 10:11 pm - Bernhard Hailer

- Status changed from New to Feedback

Have you been able to resolve this on your own since you submitted this?

Have you tried with a recent version since you submitted this?

If you haven't, and if you're still having this issue, please refer to the Wiki "[[How To Report Issues]]" and provide a debug log. Thanks!

#3 - 09/10/2020 04:37 pm - Bernhard Hailer

- Status changed from Feedback to Closed

No more feedback by submitter. We have to assume that the problem came from attempting to communicate with an unsupported radio.

Please let us know in case the ticket should be reopened. But please also review #2253.

#4 - 09/10/2020 04:38 pm - Bernhard Hailer

- Platform changed from Windows to MacOS