

CHIRP - Bug # 5465

Status:	New	Priority:	Normal
Author:	Fotios Angelopoulos	Category:	
Created:	12/29/2017	Assignee:	
Updated:	02/10/2020	Due date:	
Chirp Version:	daily		
Model affected:	QYT KT-7900D		
Platform:	All		
Subject:	QYT KT-7900D settings missing		
Description			
<p>ANI code (Menu 48) is only programmed through PC software, and this function is not included in Chirp's settings, so ANI code can't be changed by user through Chirp.</p> <p>Also, "Roger Beep" that is found in Chirp's Basic Settings isn't a capability of QYT KT-7900D.</p> <p>Backlight timer (Menu 8) doesn't work on transceiver at all (just for note).</p> <p>Regards</p>			

History

#1 - 02/10/2020 05:36 pm - Bernhard Hailer

- Tracker changed from New Model to Bug
- Subject changed from QYT KT-7900D to QYT KT-7900D settings missing
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Model affected set to QYT KT-7900D
- Platform set to All