

CHIRP - Bug # 5477

Status:	Closed	Priority:	Normal
Author:	Todd Bina	Category:	
Created:	01/03/2018	Assignee:	
Updated:	09/10/2020	Due date:	
Chirp Version:	daily		
Model affected:	Baofeng GT-3TP		
Platform:	Windows		
Subject:	Baofeng GT-3TP not transmitting		
Description	<p>I used chirp and was able to download the VHF Marine channels provided from the program. The radio will Rx from our base station however it will not Tx back. No feedback or anything from the Baofeng what so ever. Is there an issue with the Marine frequencies? My UV5 works great, just got new radios and thought everything would be fine.</p>		

History

#1 - 01/04/2018 04:26 pm - Jim Unroe

What do you mean "will not Tx back"? When the PTT button is pressed, is there an indication of transmitting on the LCD display and from a red LED on the front of the radio? Does the "base station" use selective squelch? If it does, have you programmed the UV-5R to TX the matching CTCSS tone?

Jim KC9HI

#2 - 05/17/2018 10:39 am - Peter Speakman

We have been having issues with the GT-3TP where it will transmit and receive in frequency mode but only receive in channel mode. It looks to be a large batch of radios that have this issue. Mine work fine but some of my friends are on their 4th replacement.

#3 - 05/17/2018 11:58 am - Peter Speakman

OK so today I looks like I have managed to get one working, unfortunately I don't know a great deal about CHIRP but I managed to get it working using the UV5 software and setting the max UHF frequency to 520 which not lets it transmit in channel mode. :)

#4 - 05/06/2020 10:17 pm - Bernhard Hailer

- Status changed from New to Feedback
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Model affected changed from (All models) to Baofeng GT-3TP

Have you been able to resolve this on your own since you submitted this?

Have you tried with a recent version since you submitted this?

If you haven't, and if you're still having this issue, please refer to the Wiki "[[How To Report Issues]]" and provide a debug log. Thanks!

#5 - 09/10/2020 05:12 pm - Bernhard Hailer

- Status changed from Feedback to Closed

Closed due to lack of clarity and feedback by submitter.