

CHIRP - Bug # 5495

Status:	New	Priority:	Urgent
Author:	fabio savorelli	Category:	
Created:	01/14/2018	Assignee:	Dan Smith
Updated:	01/15/2018	Due date:	
Chirp Version:	0.4.0		
Model affected:	ICOM ID 51		
Platform:	Windows		
Subject:	ICOM ID 51		
Description			
<p>DEAR CHIRP THANKS IN ADVANCE FOR YOUR WORK I SEE THAT WITH LAST CHIRP (JAN 4 2018) I CAN PROGRAM MY ICOM ID 51 . IM VERY HAPPY BUT THERE ARE A PROBLEM ON ALPHA CHANNELS . I PUT SHIFT -0.600000 AND I TRANSFER TO RADIO . WHEN I PUSH THE PTT I SEE DIFFERENT FREQUENCY ON TX . FOR EXAMPLE : 145.737,5 - 0.60000 MUST ON PTT TX ON 145,137,5 , BUT TRASMITTING FREQUENCY IS 145,25750...SO SHIFT IS 0,480000 FOR EXAMPLE : 430.312,5 + 1.60000 MUST ON PTT TX ON 431,912,5 , BUT TRASMITTING FREQUENCY IS 431,592,5 SO SHIT IS 1.28000 THIS KIND OF MISTAKE ONLY ON ALL ALPHA CHANNEL. ON NORMAL FREQUENCY UHF VHF ALL ARE OK . ONLY ALPHA CHANNELS. I THINK PROGRAM ARE NOT ABLE TO MAKE MINUS 0.600 WHEN AFTER LAST 3 NUMBER OF FREQ IT FIND ANOTHER NUMBER AS ALPHA CHANNELS THANKS IN ADVANCE FOR ALL . JUST TO INFORM YOU ALSO THAT WITH LAST CHIRP (JAN 4 2018) NOW I CAN PROGRAM ALSO WOUXUN KG-UV8D PLUS. WITH WOUXUN ALL OK ALL WORK ALSO ALPHA CHANNELS. MY THANKS . IU2ACH (FABIO) FROM ITALY</p>			

History

#1 - 01/15/2018 03:39 am - fabio savorelli

please check importing from radio with icom software problem describe in my report ...look alpha channel

Yesterday i memorize ico id 51 using chirp

thanks in advance for your support...

Also today with last chirp jan 15 2018 program dont reconize icom id 51 ...it say problem it com port..but com port working ...i used orginal software...

many thanks for all...

IU2ACH Fabio (Italy)