

CHIRP - Bug # 5565

Status:	Closed	Priority:	Normal
Author:	vincent payelle	Category:	
Created:	02/11/2018	Assignee:	
Updated:	05/09/2020	Due date:	
Chirp Version:	daily		
Model affected:	Baofeng UV-9R		
Platform:	Windows		
Subject:	Programation du baofeng UV-9R		
Description	<p>Bonjour comment programmer le baofeng UV-9R avec CHIRP ? Le câble de programmation est bien reconnue , mais rien a faire avec CHIRP , il reconnait pas l'UV-9R. D avance merci de votre aide .</p> <p><i>Hello how to program baofeng UV-9R with CHIRP? The programming cable is well recognized, but nothing to do with CHIRP, it does not recognize the UV-9R. Thank you in advance for your help .</i></p>		

History

#1 - 03/04/2020 04:47 pm - Bernhard Hailer

- Description updated
- Priority changed from High to Normal
- Target version set to chirp-daily
- Model affected changed from UV-9R to Baofeng UV-9R

#2 - 03/04/2020 04:48 pm - Bernhard Hailer

The UV-9R is supported. Have you been able to resolve this on your own since you submitted this?
If you haven't, and if you're still having this issue, please refer to the Wiki "[[How To Report Issues]]" and provide a debug log. Thanks!

#3 - 03/04/2020 04:48 pm - Bernhard Hailer

- Status changed from New to Feedback

#4 - 05/09/2020 06:11 pm - Bernhard Hailer

- Status changed from Feedback to Closed

No more feedback by submitter.