

## CHIRP - New Model # 5711

<b>Status:</b>	Closed	<b>Priority:</b>	Normal
<b>Author:</b>	Enrico Suave	<b>Category:</b>	
<b>Created:</b>	04/10/2018	<b>Assignee:</b>	
<b>Updated:</b>	09/08/2021	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Equipment Loan Offered:</b>	No		
<b>Subject:</b>	Baofeng BF-999s Plus (KS-317)		
<b>Description</b>	the Baofeng BF-999s (no PLUS) works with most of the same programming software that that the Baofeng BF-888s uses, but the 999s Plus does not. Usually when I try the same software, including CHIRP, I get a "connection refused by radio" error message.		
<b>Related issues:</b>	duplicated by New Model # 5927: Baofeng BF-999 Plus <span style="float: right;">Closed 07/05/2018</span>		

### History

#### #1 - 05/15/2020 10:05 pm - Bernhard Hailer

- Subject changed from Baofeng BF-999s Plus (KS-317) Request to Baofeng BF-999s Plus (KS-317)
- Status changed from New to Feedback
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily

Who is the maker of the KS-317? Is it the same as the BF-999S+? I searched for it and can't find it.

#### #2 - 09/06/2021 04:50 am - Jim Unroe

Duplicates issue #5253

#### #3 - 09/08/2021 08:10 pm - Bernhard Hailer

- Status changed from Feedback to Closed