

CHIRP - Bug # 5955

Status:	Closed	Priority:	Normal
Author:	adriaan de beer	Category:	
Created:	07/17/2018	Assignee:	
Updated:	05/09/2020	Due date:	
Chirp Version:	daily		
Model affected:	Kenwood TK-7102		
Platform:	All		
Subject:	Kenwood TK-7102, Radio refused program mode		
Description	TRYING TO ENTER PROGRAMMING MODE ON MY KENWOOD TK7102,USING PORT 08 ON CHIRP AND PORT 08 IN WINDOWS STILL GET AN ERROR HAS OCCURED Radio refused program mode.....I HAVE TRIED 3 DIFFERENT CABLES ALREADY AND KEEPS GETTTING SAME ERROR,PLEASE HELP.		

History

#1 - 01/27/2020 02:42 pm - Bernhard Hailer

- Subject changed from PROGRAMMING MODE to Kenwood TK-7102, Radio refused program mode
- Status changed from New to Feedback
- Priority changed from Urgent to Normal
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Model affected changed from (All models) to Kenwood TK-7102
- Platform changed from Windows to All

Have you been able to resolve this on your own? If not, please read the Wiki: [\[\[How To Report Issues\]\]](#), and provide a debug log. Perhaps then we can help.

#2 - 05/09/2020 10:50 pm - Bernhard Hailer

- Status changed from Feedback to Closed

No more feedback by submitter.