

## CHIRP - Bug # 6061

<b>Status:</b>	Feedback	<b>Priority:</b>	Normal
<b>Author:</b>	Jeff Jennings	<b>Category:</b>	
<b>Created:</b>	08/28/2018	<b>Assignee:</b>	
<b>Updated:</b>	09/13/2020	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Model affected:</b>	Baofeng UV-82C, UV-5HP		
<b>Platform:</b>	Windows		
<b>Subject:</b>	Baofeng UV-82C, UV-5HP cannot be programmed manually after Chirp use on them		
<b>Description</b>	<p>When I use CHIRP to program my radio I cannot alter the programming in the radio from the radio's keypad. This is an issue with the Baofeng UV-82C and the Baofeng UV-5HP. The only way I can alter the programming is to use CHIRP and hook the radio back up to the computer, it cannot be altered in the field.</p>		

### History

#### #1 - 05/10/2020 07:11 pm - Bernhard Hailer

- Subject changed from Chirp Programming to Baofeng UV-82C, UV-5HP cannot be programmed manually after Chirp use on them
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Model affected changed from UV-82C and UV-5HP to Baofeng UV-82C, UV-5HP

#### #2 - 09/13/2020 04:11 pm - Bernhard Hailer

- Status changed from New to Feedback

Is possibly the keypad lock enabled in your radios? I believe (at least for the 82c) it's in menu 24.