

CHIRP - Bug # 6181

Status:	Closed	Priority:	Normal
Author:	Henry Spratt	Category:	
Created:	10/21/2018	Assignee:	
Updated:	03/25/2020	Due date:	
Chirp Version:	daily		
Model affected:	Baofeng GT-5TP		
Platform:	Windows		
Subject:	Baofeng GT-5TP		
Description			
I require settings for the baofeng gt-5tp radio.			

History

#1 - 02/11/2020 01:23 pm - Bernhard Hailer

- Tracker changed from New Model to Bug
- Subject changed from my gt-5tp baofeng. to Baofeng GT-5TP
- Assignee deleted (Henry Spratt)
- Priority changed from High to Normal
- Target version changed from 0.4.1 to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Model affected set to Baofeng GT-5TP
- Platform set to Windows

Try using the Baofeng UV-82HP selection in Chirp and report back.

If you're still having this issue, please refer to the Wiki [\[\[How To Report Issues\]\]](#) and provide a debug log. Thanks!

#2 - 03/25/2020 10:28 pm - Bernhard Hailer

- Status changed from New to Closed

No more feedback by submitter.