

CHIRP - Bug # 6187

Status:	Closed	Priority:	Normal
Author:	Kourosh Delpak	Category:	
Created:	10/23/2018	Assignee:	
Updated:	02/25/2020	Due date:	
Chirp Version:	daily		
Model affected:	Baofeng UV-5R		
Platform:	Windows		
Subject:	Baofeng UV-5R UHF/VHF problem		
Description	<p>Hi Guys I Found Bug On Baofeng UV5R When The I Want Unlimited To UHF And VHF Its Limited When I Go On 390Mhz And Selected Menu I Saw Its Vhf This Is Big Problem and Because Of This Lower Than The 400Mhz Rx And Tx Very Poor Because It Use VHF Filters By The Way In VFO Mode When dual Display Band Are UHF Frequncys The Upper Is 390Mhz And The Downer Freq Is 450Mhz For Example When Push Menu Buttom On VFO Mode Its Very Work PERFECT!!! And When The Signal Is Stop Its Go Uses VHF Filters But When Push Menu Buttom And See Menu 33 UHF And Push Over Moni Buttum It Stay And Uses UHF FILTER By The Way I Recive UHF SATCOM You Can Search It On Youtube And Instagram RadioFrequency.ep</p> <p>Hope You Can SOLVED This Bug</p> <p>Best Regards Kourosh Delpak</p>		
Related issues:	duplicated by Bug # 6189: Baofeng UV-5R UHF/VHF problem Closed 10/23/2018		

History

#1 - 10/23/2018 03:54 pm - Kourosh Delpak

Kourosh Delpak wrote:

Hi Guys I Found Bug On Baofeng UV5R When The I Want Unlimited To UHF And VHF Its Limited When I Go On 390Mhz And Selected Menu I Saw Its Vhf This Is Big Problem and Because Of This Lower Than The 400Mhz Rx And Tx Very Poor Because It Use VHF Filters By The Way In VFO Mode When On dual Display Band Are UHF Frequncys The Up Is 390Mhz And The Down Freq Is 450Mhz For Example When Push Menu Buttom On VFO Mode Its Very Work PERFECT!!! And When The Signal Is Stop Its Go Uses VHF Filters But When Push Menu Buttom And See Menu 33 UHF And Push Over Moni Buttum It Stay And Uses UHF FILTER By The Way I Recive UHF SATCOM You Can Search And Watch My Video On Youtube(Kourosh Delpak) And Instagram (RadioFrequency.ep)

Hope You Can SOLVED This Bug

Best Regards

Kourosh Delpak EP2XX 73

#2 - 01/23/2020 01:29 pm - Bernhard Hailer

- Subject changed from UHF/VHF to Baofeng UV-5R UHF/VHF problem

- Status changed from New to Feedback

- Model affected changed from UV5R to Baofeng UV-5R

If I understand you correctly, then you are complaining about a limitation you have on your Baofeng UF-5R, not about any Chirp functionality. Chirp has no means to modify how a radio works or what the firmware / RF hardware in it can do.

Please let us know if your problem is with a Chirp feature, or with the radio itself; otherwise we'll close this issue soon. Thanks!

#3 - 02/25/2020 07:49 pm - Bernhard Hailer

- *Status changed from Feedback to Closed*

- *Target version set to chirp-daily*