

CHIRP - Bug # 6267

Status:	Closed	Priority:	Normal
Author:	george TOM	Category:	
Created:	12/01/2018	Assignee:	
Updated:	03/04/2020	Due date:	
Chirp Version:	daily		
Model affected:	CRT 279UV		
Platform:	Windows		
Subject:	CRT-279UV clone QYT KT7900D does not enter clone mode		
Description	message : RADIO DID NOT ENTER CLONE MODE !! MCU Version: VC5302		
Related issues:	duplicates New Model # 6211: CRT-279UV (clone of QYT KT7900D)		Feedback 11/02/2018

History

#1 - 02/28/2020 12:43 pm - Bernhard Hailer

- Tracker changed from New Model to Bug
- Subject changed from CRT-279UV clone QYT KT7900D to CRT-279UV clone QYT KT7900D does not enter clone mode
- Status changed from New to Feedback
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Model affected set to QYT KT7900D
- Platform set to Windows

Two things.

- 1) Please try with a recent build of Chirp.
- 2) If if you're still having this issue, please refer to the Wiki How To Report Issues and provide a debug log. Thanks!

#2 - 03/04/2020 10:23 am - Bernhard Hailer

Please refer to the Wiki [\[\[How To Report Issues\]\]](#) and provide a debug log. Thanks!

And please clarify: is your radio a QYT KT7900D or a CRT-279UV?

#3 - 03/04/2020 10:34 am - Bernhard Hailer

- Status changed from Feedback to Closed
- Model affected changed from QYT KT7900D to CRT 279UV

Duplicates #6211. Please leave further feedback there. Thanks!

Files

Sans titre 2.jpg

13.2 kB

12/01/2018

george TOM