

CHIRP - Bug # 6401

Status:	Feedback	Priority:	Normal
Author:	Don Berkholtz	Category:	
Created:	01/23/2019	Assignee:	
Updated:	05/12/2020	Due date:	
Chirp Version:	daily		
Model affected:	(All models)		
Platform:	Windows		
Subject:	Slow Read Error on AnyTone AT-5888UV		
Description	<p>Not sure if this is a Chirp issue or Windows 10 issue. Ive been using Chirp to program my AnyTones AT-5888UV. When reading the programming on the radio, Ive been getting a "Slow Read Error" and locks up the radio and cannot get the programming. Ive used 2 computers that has the lastest version of Chirp do this. The 3rd computer worked but was running an older version of Chirp. I had even thought maybe a bad cable, but all 3 computers work with the AnyTone software. Also noticed when using Chirp, it takes longer than normal to process the information. Very slow. Any help would be truly appreciated.</p>		
Related issues:	related to Bug # 631: Anytone AT-5888UV Fails to Download Closed 02/27/2013		

History

#1 - 05/12/2020 07:13 pm - Bernhard Hailer

- Status changed from New to Feedback
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily

Have you tried with a recent version since you submitted this? 0.4.0 is pretty old.

If you haven't, and if you're still having this issue, please refer to the Wiki "[[How To Report Issues]]" and provide a debug log. Thanks!