

CHIRP - Bug # 7107

Status:	Closed	Priority:	Normal
Author:	John Boal	Category:	
Created:	09/22/2019	Assignee:	
Updated:	10/01/2020	Due date:	
Chirp Version:	daily		
Model affected:	QYT KT-7900D		
Platform:	Windows		
Subject:	QYT KT-7900D Settings Page Fails to Load		
Description			
<p>Unable to load the settings page for this radio - it used to work earlier this year... not sure when it stopped working. Attached are screen shot and debug log.</p> <p>Please figure out what build broke this and fix it! Am a developer, have several of these radios, and am willing to help troubleshoot and/or debug K9JEB</p>			

History

#1 - 09/22/2019 10:17 am - John Boal

- File *QYT_KT7900D_K9JEB.img* added

adding my radio image file

#2 - 09/22/2019 11:16 am - John Boal

Confirmed also broken on CHIRP daily-20190905 linux (ubuntu)
Definitely working on March releases in Windows - so something broke since then.

#3 - 04/19/2020 03:10 pm - Bernhard Hailer

- Status changed from *New* to *Feedback*
- Priority changed from *High* to *Normal*
- Target version set to *chirp-daily*

This type of problem is usually caused by an out-of-range parameter in the radio.
Do you remember what you changed last? Try to restore it, and search for parameters which aren't looking correct.

#4 - 10/01/2020 03:25 pm - Bernhard Hailer

- Status changed from *Feedback* to *Closed*

No more feedback by submitter.

Remark: you may want to ask on the Chirp Users mailing list: there's a good chance that someone there can help you.

Files

20190922_debug.log	32.3 kB	09/22/2019	John Boal
ChirpSettingsFailureKT7900d.jpg	51.5 kB	09/22/2019	John Boal
QYT_KT7900D_K9JEB.img	16.2 kB	09/22/2019	John Boal