

CHIRP - New Model # 7555

Status:	Closed	Priority:	Normal
Author:	William Curlew	Category:	
Created:	01/13/2020	Assignee:	
Updated:	03/09/2021	Due date:	
Chirp Version:	daily		
Equipment Loan Offered:	No		
Subject:	Cannot clone FT-450 (NON-D model)		
Description	<p>Get error message "Failed to communicate with radio: Unable to read block 0 expected 6 got 4" no matter what the radio's cat setting are set to. Also noted in the FT-450D manual that you cannot clone between a 450 and a 450D, so I assume they are different. Only the 450D shows up in the list, please add support for the 450.</p>		
Related issues:	duplicates New Model # 7135: Yaesu FT-450 (not FT-450D)		Feedback 09/30/2019

History

#1 - 01/18/2020 04:23 pm - Bernhard Hailer

- Status changed from New to Closed
- Target version set to chirp-daily

Request already made, see #7135.

#2 - 03/08/2021 10:57 am - Bernhard Hailer

There is a possible solution (a firmware upgrade) suggested in #7839; please check and see whether it helps.

#3 - 03/08/2021 03:25 pm - William Curlew

The last firmware for the FT450 NON-D version was V0228. You cannot load the 450D version V-244 firmware into the non-D radio without bricking it.

Bill Curlew

#4 - 03/09/2021 03:04 pm - Bernhard Hailer

Thanks for the clarification. A similar comment was made on #7135, where this discussion should continue.

Files

debug.log	24.8 kB	01/13/2020	William Curlew
-----------	---------	------------	----------------