

CHIRP - Bug # 7931

Status:	New	Priority:	Normal
Author:	Dixon Barthel	Category:	
Created:	05/31/2020	Assignee:	Dan Smith
Updated:	05/31/2020	Due date:	
Chirp Version:	daily		
Model affected:	FT-818ND		
Platform:	Linux		
Subject:	FT-817/8 Freq Step issue		
Description			
<p>First, thanks for making this program available for us to use. I have a problem, however, with my FT-818. When I download from the radio, everything downloads just fine. When, however, I attempt to change ANY of the VFO (HF) Tune Steps, my only options are 5 KHz or greater. In the versions from 2019 this was not a problem, but now, every new version has the same issue. Is there a fix or a workaround?</p> <p>Thanks again.</p> <p>Dixon, K3WNS</p>			

History
