

CHIRP - Bug # 7959

Status:	Feedback	Priority:	Normal
Author:	Michael Schreiner	Category:	
Created:	06/07/2020	Assignee:	
Updated:	06/11/2020	Due date:	
Chirp Version:	daily		
Model affected:	Wouxun KG-UV6D		
Platform:	Windows		
Subject:	Wouxun KG-UV6D E		
Description			
Hi I get an Error b reading am Wouxun KG-VD6D Failed to communicate with radio: Failed to read full block (67!=68). Can ou help me?			
Related issues:			
related to New Model # 4153: Wouxun KG-UVD1P Branded as 'Bravus'		New	10/21/2016

History

#1 - 06/07/2020 10:54 am - Michael Schreiner

KG-UD6D

#2 - 06/08/2020 03:33 pm - Bernhard Hailer

- Status changed from New to Feedback

- Model affected changed from Wouxun to Wouxun KG-UV6D

Is it actually a Wouxun KG-UV6D?

Could you please provide a debug log as described in the Wiki: "[[How To Report Issues]]"? Thanks!

#3 - 06/10/2020 10:29 pm - Michael Schreiner

- File *debug.log* added

Hi

I have now the debug.log. may you can help me.

Michael

#4 - 06/10/2020 10:34 pm - Michael Schreiner

- File *20200611_073157_resized.jpg* added

Michael Schreiner wrote:

Hi

I have now the debug.log. may you can help me.

Michael

#5 - 06/11/2020 12:56 pm - Bernhard Hailer

I found a ticket with a similar issue on a Wouxun KG-UVD1P (#4153).

Hopefully, one of our developers can have a look.

Files

debug.log	28.1 kB	06/10/2020	Michael Schreiner
20200611_073157_resized.jpg	610.6 kB	06/10/2020	Michael Schreiner