

## CHIRP - New Model # 7971

<b>Status:</b>	New	<b>Priority:</b>	Normal
<b>Author:</b>	Santi Fernandez	<b>Category:</b>	
<b>Created:</b>	06/10/2020	<b>Assignee:</b>	
<b>Updated:</b>	06/11/2020	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Equipment Loan Offered:</b>	No		
<b>Subject:</b>	Icom IC-F31GT-1		
<b>Description</b>	se podria incluir el modelo de ICOM ic-F31GT-I  <i>the Icom IC-F31GT-I model could be included</i>		
<b>Related issues:</b>	duplicated by New Model # 8193: Icom IC-F31GT-L		<b>Closed</b> <b>08/22/2020</b>

### History

#### #1 - 06/11/2020 11:51 am - Bernhard Hailer

- Tracker changed from Bug to New Model
- Subject changed from icom to Icom IC-F31GT-1
- Description updated
- Equipment Loan Offered set to No