

## CHIRP - New Model # 8137

<b>Status:</b>	Feedback	<b>Priority:</b>	Normal
<b>Author:</b>	Mark Eastus	<b>Category:</b>	
<b>Created:</b>	07/27/2020	<b>Assignee:</b>	
<b>Updated:</b>	01/20/2021	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Equipment Loan Offered:</b>	No		
<b>Subject:</b>	Leixen UV-25D		
<b>Description</b>			
<p>I recently purchased the Leixen UV-25D Dual Band radio. The seller provided a download link for the software, however, the program will not open. This model is not on your to do list. Is this something you will be getting to anytime soon?</p> <p>Thank you.</p> <p>Mark Eastus <a href="mailto:jmrenucci55@gmail.com">jmrenucci55@gmail.com</a></p>			
<b>Related issues:</b>			
duplicated by New Model # 8239: Leixen UV-25D		<b>Closed</b>	<b>07/27/2020</b>

### History

#### #1 - 01/19/2021 11:27 pm - Jan Vincent Macasieb

is there an update about this product? i bought one and the software in their webste is not working. when i read the radio, the radio resets.

#### #2 - 01/20/2021 04:40 pm - Bernhard Hailer

- Status changed from New to Feedback

- Target version set to chirp-daily

Sorry, no update. The addition of a new radio to Chirp requires two things:

- 1) a volunteer developer who takes the task to work on this driver,
- 2) availability of test equipment, such as a loaner radio (see [\[\[Rules For Loaning A Radio\]\]](#)).

Unfortunately, you need to wait until both conditions have been met.

Or, you could decide to get your hands dirty yourself - check Wiki, "[\[\[Developers\]\]](#)".