

## CHIRP - New Model # 8317

<b>Status:</b>	Feedback	<b>Priority:</b>	Normal
<b>Author:</b>	Jennifer Wendelin	<b>Category:</b>	
<b>Created:</b>	10/07/2020	<b>Assignee:</b>	
<b>Updated:</b>	10/12/2020	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Equipment Loan Offered:</b>	No		
<b>Subject:</b>	QYT KT-9800+		
<b>Description</b>	<p>Am I doing something wrong? I can't get the program to access the radio. I try turning the radio on and then immediately trying to access the radio and get the same response (None) as just trying to access the radio with it already on. I am using the manufacturers programming cable and have downloaded and installed the driver files needed and am using the latest version of Chirp. I can find very little information on the web about programming this radio, what there is has not been helpful at all. I'm hoping someone can help me because programming this radio manually is a major pain in every orifice possible! Help?</p>		

### History

#### #1 - 10/12/2020 06:09 pm - Bernhard Hailer

- Tracker changed from Bug to New Model
- Subject changed from QYT KT-9800PLUS Programming to QYT KT-9800+
- Status changed from New to Feedback
- Assignee deleted (Jennifer Wendelin)
- Equipment Loan Offered set to No

Hello Jennifer, the QYT KT-9800+ is currently not supported (see list of [\[\[Supported Radios\]\]](#)).

I converted your ticket into a New Model Request.