

CHIRP - Bug # 8407

Status:	Closed	Priority:	Normal
Author:	Brad Schuler	Category:	
Created:	11/07/2020	Assignee:	Brad Schuler
Updated:	12/02/2020	Due date:	
Chirp Version:	daily		
Model affected:	AnyTone 5888UV		
Platform:	All		
Subject:	Add remaining channel attributes and valid tuning steps to AnyTone 5888UV		
Description			
<p>The following channel attributes are missing for the AnyTone 5888UV radio:</p> <ul style="list-style-type: none">- Duplex: off- Busy channel lockout- Optional signal selection (DTMF, 2-tone, 5-tone)- Reverse- Compander- Talkaround- PTT ID- Squelch with optional signal- Use custom CTCSS for Tx and/or Rx <p>The tuning steps allowed are incorrect.</p>			

Associated revisions

Revision 3418:0a0f0d71c383 - 11/20/2020 08:11 pm - Brad Schuler

[AnyTone 5888UV] Add simple squelch mode & additional file identifier and add extra channel attributes

Related to issues #1491, #2989, #3653, #6633 and #8407

(#1491, #2989, #3653, #6633)

Set the radio's squelch mode to CTCSS/DCS Tones instead of Carrier when the receive tone mode is set.
Recognize a file image from this radio when no metadata is present.

(#8407)

Add the following channel attributes

- Tuning steps
- Duplex: off
- Busy channel lockout
- Optional signal selection (DTMF, 2-tone, 5-tone)
- Reverse
- Compander
- Talkaround
- PTT ID
- Squelch with optional signal
- Use custom CTCSS for Tx and/or Rx

History

#1 - 12/02/2020 07:58 pm - Bernhard Hailer

- Status changed from New to Closed

See #1491.