

CHIRP - Bug # 8963

Status:	New	Priority:	High
Author:	rafael martinez	Category:	
Created:	04/05/2021	Assignee:	
Updated:	04/05/2021	Due date:	
Chirp Version:	daily		
Model affected:	bf-888		
Platform:	Windows		
Subject:	bf-888 get no power after programming,		
Description			
<p>Dear sirs</p> <p>I bought 4 BF-888s radios, one of which I measured before connecting to the PC, with power at 1.8 watts. so they were ok. I read one of them and saved the original programing as reference, later using the chirp, I programmed all 4 radios with custom frequencies and now none of the radios give power the frequencies are right (receiver ok) but no power, reading in a Motorola service monitor they give 0.3 rf mili volts and spectrum analyzer is perfect in freq, but then again no power.</p> <p>So something should happened at programming cause all the radios are the same. Please can you look for a solution, I think something in the software corrupted the memory inhibiting the power output, can you make a patch to solve the issue.</p> <p>I read in several issues blogs, the new firmware has different problems, can this be it, even a lady complaint was: the radio is now bricked</p> <p>Need help.</p> <p>Best regards</p> <p>Rafael Martinez HK3RU</p>			

History
