

CHIRP - Bug # 9461

| | | | |
|--|------------------------------|------------------|--------|
| Status: | Feedback | Priority: | Normal |
| Author: | MICHEL ANTOINE DRIVET AMADOR | Category: | |
| Created: | 10/20/2021 | Assignee: | |
| Updated: | 06/09/2022 | Due date: | |
| Chirp Version: | daily | | |
| Model affected: | Kenwood TK-372G | | |
| Platform: | Windows | | |
| Subject: | KENWOOD TK732G | | |
| Description | | | |
| CHIRP DOESN'T READ THE RADIO IDENTIFIES IT CORRECTLY BUT AT THE END OF THE READING PROCEDURE SENDS AN ID ERROR | | | |

History

#1 - 10/21/2021 05:23 pm - MICHEL ANTOINE DRIVET AMADOR

- File debug.log added

Wrong Kenwood radio, ID or unknown variant, see LOG output. THIS ERROR SHOWS ON SCREEN

#2 - 10/22/2021 08:30 pm - MICHEL ANTOINE DRIVET AMADOR

- File debug.log added

#3 - 11/07/2021 05:11 pm - MICHEL ANTOINE DRIVET AMADOR

- File debug.log added

WITH THE NEW VERSION SAME ERROR

#4 - 05/12/2022 09:49 pm - Bernhard Hailer

- Priority changed from High to Normal

- Model affected changed from TK372G to Kenwood TK-372G

#5 - 05/13/2022 03:20 pm - Pavel Milanec

Hi OM, thanks for the debug log. (driver's author here)

The operation fails as the last byte of the ident string are not the same, look it for yourself:

DEBUG: Full ident string is:

DEBUG: 000: 50 33 37 32 30 06 fb *f1* P3720...

DEBUG: Starting the download from radio

DEBUG: Wrong Kenwood radio, ID or unknown variant

DEBUG: 000: 50 33 37 32 30 06 fb *00* P3720...

That means that the radio has the TRUNKING addon board installed. Reviewing the drivers identification schema:

"P3720\x06": (32, 450, 470, "K")
"P3720\x07": (32, 470, 490, "K1")
"P3720\x08": (32, 490, 512, "K2")
"P3720\x09": (32, 403, 430, "K3")

You can see it's like a "K" variant and must work from 450 to 470 Mhz, it's supported.

Also, the driver does not support radios with the TRUNKING addon installed (last f1 byte means that) as it changes the memory handling a bit.

If you can access the OEM software please read it, deactivate the TRUNKING option and upload the programming again.

I must work with chirp then.

Cheers, Pavel CO7WT.

#6 - 05/13/2022 03:20 pm - Pavel Milanes

- Status changed from New to Feedback

#7 - 06/09/2022 12:54 am - Bernhard Hailer

Please let us know whether this response helped, so that we can close the ticket.

Files

| | | | |
|-----------|---------|------------|------------------------------|
| debug.log | 26.2 kB | 10/21/2021 | MICHEL ANTOINE DRIVET AMADOR |
| debug.log | 41.3 kB | 10/22/2021 | MICHEL ANTOINE DRIVET AMADOR |
| debug.log | 31.3 kB | 11/07/2021 | MICHEL ANTOINE DRIVET AMADOR |