

CHIRP - Bug # 9487

Status:	Rejected	Priority:	Normal
Author:	John Chappell	Category:	
Created:	10/25/2021	Assignee:	
Updated:	03/05/2022	Due date:	
Chirp Version:	daily		
Model affected:	(All models)		
Platform:	Windows		
Subject:	usb-serial driver		
Description			
<p>I am using is a new Samsung Galaxy Book Pro model:NP340XLA-KA3US (owned less than a week) it has only 1 USB port. I am trying to run CHIRP (daily update install) the ch340 driver will not install. I have verified the BaoFeng cable uses the CH340 when run CHIRP & I try to download the radio it shows com9 but gives [error 31], I have searched everywhere, even called Samsung, I have had no luck anywhere. I can not find any contact information for the website where you download the ch341 drivers. www.Miklor.com</p> <p>I seriously need help getting this driver to install.</p> <p>Thank you, John</p>			

History

#1 - 03/05/2022 02:36 am - Bernhard Hailer

- Status changed from New to Rejected

Unfortunately, this is not in the scope of the Chirp team.

This is a question best asked on the [mailing list](#).

You might get (much) quicker feedback there.