

CHIRP - Bug # 9525

Status:	Closed	Priority:	Normal
Author:	Jorge Ortiz HP8-GAL	Category:	
Created:	11/06/2021	Assignee:	Jim Unroe
Updated:	04/16/2022	Due date:	
Chirp Version:	daily		
Model affected:	Baofeng UV-5R		
Platform:	All		
Subject:	estandar rango en Baofen UV-5R (expand range on Baofeng UV-5R)		
Description	LA VENTANA DE CONFIGURACION NE APARESE EN BLANCO, CON EL PROGRAMA CHIRP <i>THE CONFIGURATION WINDOW IS [NOT] BLANK, WITH THE CHIRP PROGRAM</i>		

History

#1 - 11/07/2021 06:39 am - Jim Unroe

Jorge Ortiz HP8-GAL wrote:

LA VENTANA DE CONFIGURACION NE APARESE EN BLANCO, CON EL PROGRAMA CHIRP

This is usually the result of the radio having one or more settings that are out-of-range (which trips up CHIRP). Usually the debug.log file can be used to determine which setting(s) are misbehaving. However it would be more convenient if you would attach a freshly downloaded CHIRP Radio Images (*.img) file from your radio.

Jim KC9HI

#2 - 11/07/2021 12:21 pm - Bernhard Hailer

- Tracker changed from New Model to Bug
- Subject changed from *estandar rango en Baofen UV-5R* to *estandar rango en Baofen UV-5R (expand range on Baofeng UV-5R)*
- Description updated
- Model affected set to *Baofeng UV-5R*
- Platform set to *All*

#3 - 04/16/2022 05:37 am - Bernhard Hailer

- Status changed from *New* to *Closed*

No more feedback by submitter.