

CHIRP - Bug # 9539

Status:	Closed	Priority:	Normal
Author:	Cesar Williams	Category:	
Created:	11/12/2021	Assignee:	
Updated:	11/18/2021	Due date:	
Chirp Version:	daily		
Model affected:	Baofeng BF-888S		
Platform:	All		
Subject:	Baofeng 888S-Squelch level		
Description	<p>I put the Squelch level to 0 and write it to the radio. Now, the green led is always ON. I try to change it through the software but no response from radio message is shown. Before i noticed this message when i try to read from the radio and the channel is busy so I change the channel to a free one and do the configuration. Now all the channels have a green led on so always the no response from radio is shown. Any help in this issue?</p>		
Related issues:	duplicates Bug # 9497: Baofeng 888S-Squelch level Closed 10/29/2021		

History

#1 - 11/18/2021 12:28 pm - Bernhard Hailer

- Status changed from New to Closed
- Priority changed from Urgent to Normal
- Model affected changed from Baofeng 888S to Baofeng BF-888S
- Platform changed from Windows to All

Please don't copy tickets from other people and create duplicates from it: it creates unnecessary clutter which is hard to maintain. Thanks.

Check on ticket #9497 for possible help.