

CHIRP - Bug # 9625

| | | | |
|------------------------|--|------------------|-----------|
| Status: | Closed | Priority: | Normal |
| Author: | Jim Unroe | Category: | |
| Created: | 12/21/2021 | Assignee: | Jim Unroe |
| Updated: | 01/02/2022 | Due date: | |
| Chirp Version: | daily | | |
| Model affected: | BF-T8 | | |
| Platform: | All | | |
| Subject: | Baofeng BF-T8 doesn't include all 11 Weather Radio Frequencies | | |
| Description | The driver for the Baofeng BF-T8 (and similar variants) only includes 7 of the 11 weather radio frequencies. | | |

Associated revisions

Revision 3637:65242e748b5e - 01/02/2022 10:17 pm - Jim Unroe

[BF-T8] Add additional weather radio frequencies to Baofeng BF-T8

The Baofeng BF-T8 (and similar models such as the Retevis RT16) has support for 11 NOAA WX radio frequencies. Currently only 7 are supported.

This patch adds support for the 4 additional WX radio frequencies.

fixes #9625

History

#1 - 12/24/2021 12:24 pm - Jim Unroe

- Status changed from *In Progress* to *Resolved*
- % Done changed from 0 to 100

A patch has been submitted. Support should be in the next CHIRP daily build following acceptance.

Jim KC9HI

#2 - 01/02/2022 02:50 pm - Anonymous

- Status changed from *Resolved* to *Closed*

Applied in changeset commit:65242e748b5e.