

CHIRP - Bug # 9689

Status:	Closed	Priority:	Normal
Author:	Marcus Wensyel	Category:	
Created:	01/08/2022	Assignee:	
Updated:	01/08/2022	Due date:	
Chirp Version:	daily		
Model affected:	Radioddity QB25		
Platform:	Windows		
Subject:	Radioddity QB25 Error		
Description			
<p>I just received a new Radioddity QB25. I am able to read/write to it using their program, but when I try with CHIRP I get Radio Identification Failed. I am using CHIRP daily-20220103.</p>			

History

#1 - 01/08/2022 02:54 pm - Jim Unroe

- Status changed from New to Closed

Accidental duplication of #9687.

Jim

Files

debug.log	56 kB	01/08/2022	Marcus Wensyel
-----------	-------	------------	----------------