

CHIRP - New Model # 9695

Status:	Feedback	Priority:	Normal
Author:	Jose de Oliveira	Category:	
Created:	01/11/2022	Assignee:	Jose de Oliveira
Updated:	01/12/2022	Due date:	
Chirp Version:	daily		
Equipment Loan Offered:	No		
Subject:	QYT KT-8900RE will not enter clone mode		
Description	<p>CHIRP daily-20220103 Windows 10 Home single language (PT-BR) USB Programming cable (works in factory programming software) QYT KT-8900RE CHIRP doesn't have the option of my QYT model "KT-8900RE", I tried the model "KT-8900R".</p> <p>When attempting to connect to the radio to read the memory out I get "Radio did not enter clone mode".</p>		

History

#1 - 01/12/2022 05:06 am - Jim Unroe

- Status changed from New to Feedback

This radio is not supported by CHIRP. It appears to me that the closest model to it that CHIRP does support is the BTECH UV-2501+220.

Jim KC9HI

Files

debug.log	43 kB	01/11/2022	Jose de Oliveira
-----------	-------	------------	------------------