

CHIRP - New Model # 9697

Status:	Closed	Priority:	Normal
Author:	Jose de Oliveira	Category:	
Created:	01/11/2022	Assignee:	Jose de Oliveira
Updated:	01/12/2022	Due date:	
Chirp Version:	daily		
Equipment Loan Offered:	No		
Subject:	QYT KT-8900RE will not enter clone mode		
Description	<p>CHIRP daily-20220103 Windows 10 Home single language (PT-BR) USB Programming cable (works in factory programming software) QYT KT-8900RE CHIRP doesn't have the option of my QYT model "KT-8900RE", I tried the model "KT-8900R". When attempting to connect to the radio to read the memory out I get "Radio did not enter clone mode".</p>		

History

- #1 - 01/12/2022 04:48 am - Jim Unroe
- Status changed from New to Closed
 - Equipment Loan Offered set to No

Duplicate of #9695

Files

debug.log	43 kB	01/11/2022	Jose de Oliveira
-----------	-------	------------	------------------