

CHIRP - Feature # 9709

Status:	Resolved	Priority:	Normal
Author:	Jim Unroe	Category:	
Created:	01/17/2022	Assignee:	Jim Unroe
Updated:	01/17/2022	Due date:	
Chirp Version:	daily		
Model affected:	Retevis RT1		
Subject:	The "new" Retevis RT1 has an additional Tx Tone setting		
Description	<p>The newer shipping Retevis RT1 models have added a Tx Tone feature (which is similar to a "roger beep"). This new setting is set to BOT (Beginning Of Transmit) from the factory. Currently CHIRP has no way of setting it to another value such as OFF. Retevis would like to have this setting added to CHIRP.</p> <p>Retevis has provided samples to use for development of support for this added setting.</p> <p>Jim KC9HI</p>		

Associated revisions

Revision 3652:82e645088417 - 01/18/2022 05:03 am - Jim Unroe

[RT1] Add support for 'Tx Tone' setting in new Retevis RT1 models

This patch adds support for the 'Tx Tone' setting that was added to recent Retevis RT1 radio models.

resolves #9709

History

#1 - 01/17/2022 05:00 pm - Jim Unroe

- Status changed from *In Progress* to *Resolved*

- % Done changed from 0 to 100

A patch has been submitted.

Jim KC9HI