

CHIRP - Bug # 9996

Status:	Closed	Priority:	Normal
Author:	Jim Unroe	Category:	
Created:	08/21/2022	Assignee:	Jim Unroe
Updated:	08/23/2022	Due date:	
Chirp Version:	daily		
Model affected:	RT76		
Platform:	All		
Subject:	[RT76] Doesn't Support Scanning		
Description	The Retevis RT76 doesn't support scanning so the "Skip" column shouldn't be available. Jim KC9HI		

Associated revisions

Revision 3730:6078f1c7b23b - 08/23/2022 12:29 am - Jim Unroe

[RT76] Retevis RT76 doesn't support scanning

This patch removes the "Skip" column since it is not needed or used.

fixes #9996

History

#1 - 08/21/2022 10:01 pm - Jim Unroe

- Status changed from *In Progress* to *Resolved*

- % Done changed from 0 to 100

A patch has been submitted. Support will be in the next CHIRP daily build following acceptance.

Jim KC9HI

#2 - 08/23/2022 12:53 am - Anonymous

- Status changed from *Resolved* to *Closed*

Applied in changeset commit:6078f1c7b23b.